

00017937.020398

FIG. 14






FIG. 15



PRIOR ART

FIG. 1






FIG. 2




FIG. 13

FIG. 3




FIG. 4




FIG. 7




FIG. 8







FIG. 9



On-Axis Response; 0.0 Hz Corner Mismatch Responses Compared to Ideal Response



On-Axis Eq'd Response; +/- 20 Hz Corner Mismatch Responses Compared to Ideal Response



09017937.020398

FIG. 10




FIG. 11




FIG. 12

